


Magnetic and mechanical considerations on SIS300 dipole structure

Stefania Farinon

INFN/GSI Meeting March 6th 2008

Last configuration




Material properties

material	Young modulus (GPa)	thermal contraction (10 ⁻³)	magnetic permeability
winding	7.5	5.63	1
Nitronic 40	192	2.4	1.002
stainless steel	220	3.0	1.02
iron	200	1.8	BH curve*0.97

NODAL SOLUTION
TIME=.1
SEQV (AVG)
DMX = .001
SMX = .006057


ANSYS 11.0
FEB 29 2008
16:35:21




0 .440E+08 .880E+08 .132E+09 .176E+09 .220E+09 .264E+09 .308E+09 .352E+09 .400E+09

Mechanical analysis: collaring

Closing of collars and keys: collars representative unit



Closing of collars and keys: force needed to close the collars




force needed to close the
collars:

7516 N per collar (3 mm thick)

or

256 tons/m each side


Closing of collars and keys: force needed to insert the keys




NO FORCE is needed
to close the keys

collars are over-
closed by 45 μm


Closing of collars and keys: Von Mises stress at the end of the operation




Closing of collars and keys: Von Mises stress in the key region




Closing of collars and keys: Von Mises stress in the pole corner



Closing of collars and keys: Von Mises stress in the pin region




Closing of collars and keys: Von Mises stress in the notch region




Mechanical analysis: iron assembly

Closing of iron shells and C-clamps: main dimensions



Closing of iron shells and C-clamps: force needed to close the iron shells




force needed to close the
iron shells:

15692 N per iron shell
(6 mm thick)

or


267 tons/m each side

Closing of iron shells and C-clamps: force needed to insert the C-clamps




C-clamps are shrink
fitted, so NO FORCE
is needed

Closing of iron shells and C-clamps: Von Mises stress at the end of the operation




Closing of iron shells and C-clamps: Von Mises stress in iron and keys




Mechanical analysis: cool-down

Cool-down to 4.2 K: Von Mises stress




Cool-down to 4.2 K: peak stress location



Mechanical analysis: energization

Energization @ 4.5 T: Von Mises stress



Azimuthal stress in conductors


LOADSTEP	Maximum azimuthal stress (MPa)	Minimum azimuthal stress (MPa)	Average azimuthal stress (MPa)
Collaring	-36	-104	-74
Cool-down	-17	-66	-46
Energization	-7	-77	-50

Distance between iron shells


LOADSTEP	Inner distance (μm)	Outer distance (μm)
Collaring	182	59
Cool-down	30	1
Energization	9	1

Magnetic analysis


hole dimensions



b3 for different hole dimensions




b5 for different hole dimensions




**we need the hole dimensions to
finalize the iron shape**


magnetic field map



fringe field



New iron hole proposal



b3 for different hole dimensions

