


# Glue Card - Top view



## Test points & jumpers

J1	Local bus enable (low=enabled)
J5	I2C #4 enable (high=enabled)
J6	I2C #3 enable (high=enabled)
J7	I2C #2 enable (high=enabled)
J8	I2C #1 enable (high=enabled)
J9	JTAG Hub address bit 0
J10	JTAG Hub address bit 6
J11	JTAG Hub output enable (low=enabled)
J12	TDO (JTAG controller output / Hub input)
J13	TCK (JTAG controller output / Hub input)
J14	TMS (JTAG controller output / Hub input)
J15	TDI (JTAG controller output / Hub input)
J16	TRIST0 (JTAG Hub output)
J17	TRIST1 (JTAG Hub output)
J18	TRIST2 (JTAG Hub output)